



**US Army Corps
of Engineers®**
Walla Walla District

Operations Division

Walla Walla District
Corps of Engineers
201 North Third Avenue
Walla Walla, Washington 99362-1876
December 18, 2007

Status Report Lower Granite Lock Located at Snake River Mile 107.5

This is a status report of the upstream gate work that is taking place at Lower Granite Lock.

Lower Granite has established a night shift for lockages using the floating bulkhead.

Commercial craft are notifying the Control Room of their estimated arrival time at the lock.

Early indications are the gate is in good condition, with minor seal damage. District structural engineers are on site to inspect the gate and hoist equipment.

Today the day shift crew assisted the structural inspection and helped perform lockages.

The inspection revealed one cracked structural member. The crack does not appear to have resulted from the cable failure. The south side ropes have been stretched and need to be replaced.

Repair efforts will take longer to repair the cracked member and to replace the damaged cables. The Project is working on repair plans and we will update the outage time as soon as possible. Meanwhile, lockages shall continue via floating bulkhead.