


## **APPENDIX A**

**Drawings and Cross Sections**

The following figures, tables, and photos show the typical repair cross sections, estimated material quantities required for the repairs, and work locations depicted on a photo taken within the proposed repair sites.


### **Site 17-1 Nebeker Drain Pipe**



Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
165	279.2	124.8	1,706	763




## **Site 17-2 Bob Harrop East**



Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
250	171.5	81.3	1,588	753




## **Site 17-3 Randy Harmon Property**




Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
230	262.1	115.1	1,262	980




## **Site 17-4 Downstream of Lorenzo Boat Ramp**



Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
2,000	0	51.2	0	3,792




Length (ft)	Cut Area (sq ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
150	109.8	0	45.6	0	253



D PHOTO: SITE 17-4  
NOT TO SCALE

## **Site 17-5 Downstream of Gasline Crossing**



**F SECTION: SITE 17-5**  
DOWNSTREAM OF GASLINE CROSSING NOT TO SCALE


Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
350	0	61.9	0	802



**A PHOTO: SITE 17-5**  
NOT TO SCALE

**Site 17-6 Robinson Location - Removed**

## **Site 17-7 Bannock Feeder**




**H SECTION: SITE 17-7**  
BANNOCK FEEDER      NOT TO SCALE

Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
100	64.5	52.3	239	269



**C PHOTO: SITE 17-7**  
NOT TO SCALE

## **Site 17-8 Pennock Location**



Length (ft)	Fill Area (sq ft)	Riprap Area (sq ft)	Fill Volume (cu yd)	Riprap Volume (cu yd)
400	194.6	88.3	2,883	1,308

