



**US Army Corps  
of Engineers®**

WALLA WALLA DISTRICT

ATTN: CENWW-DE  
201 NORTH THIRD STREET  
WALLA WALLA WA 99362-1976  
HTTP://WWW.NWW.USACE.ARMY.MIL/

**DATE:** 12/01/2017

**POC:** Kenny Koebberling  
CENWW-ODB  
Walla Walla  
District  
(509) 527-7364

**NOTICE NUMBER:** 8231-1

**LOCAL NUMBER:** 18-09  
**WTRWY/CHNL:** SNAKE RIVER

**LOCK(S):** SN 01

**EFFECTIVE:** 12/11/2017 07:00 thru 12/16/2017 17:00  
PST

**CORRECTION TO NAVIGATION NOTICE 8231:  
DELAYS IN LOCKAGE TIMES AT ICE HARBOR NAVIGATION LOCK**

McNary Lock and Dam on the Columbia River was incorrectly identified for tainter valve work 11-16 December. Navigation Notice 8231 should read as follows:

In order to perform inspections and service of the navigation lock tainter valve#3 at Ice Harbor Lock and Dam, the tainter valve will be removed from service between 0700 11 December and 1700 16 December 2017. This work will result in approximately a 20 minute delay in lockage time.

Facility affected: Ice Harbor Lock and Dam – Snake River Mile 9.7 Chief Operator on Duty: 509-543-3231 Call Sign: WUJ42

For additional information contact the Ice Harbor Chief Operator at 509-543-3231 or NWW Operations Division at (509) 527-7112/7364.

//signed//

Kenny Koebberling  
Acting Navigation Business Line Manager  
Walla Walla District