



**US Army Corps
of Engineers®**

Walla Walla District

Operations Division

Walla Walla District
Corps of Engineers
201 North Third Avenue
Walla Walla, Washington 99362-1876

January 04, 2012

Greetings,

Please use extreme caution when navigating through downstream of the approach to Ice Harbor navigation lock.

At the downstream approach to Ice Harbor navigation lock, near coffer cells, there are be some areas of shoal material building up in the navigation channel. For locations please reference sheet 10 of 10 of the most resent 2011 hydrographic surveys found on our Walla Walla District Navigation website

http://www.nww.usace.army.mil/html/OFFICES/OP/T/NAVDATA/2011AnnualConditionSurveys/For%20WEB%20FY11_HLD_CUT_v2.pdf

Recommend that boat operators call Ice Harbor for tailwater elevations before entering or exiting the downstream approach to the navigation lock to insure adequate depth for vessel.

Operations Division
Walla Walla District
Corps of Engineers
(509) 527-7115